

Repair Order Detail - Customer Copy

RO Number: 18095

RO Status: CLOSED

Customer:

Phone(s): Contact:

Vehicle: ZFFWL50A320126820

Main:

2002 456MGA

BLUE/

NATURAL

Mileage: 47,852

Service advisor: 8000

Tag number: T20

Payment type: CASH

Promised time: 06:00 PM

Promised date: 10/23/2014

Waiter: No

Estimate: 0.00

~~~~~  
A C/S CHECK ENGINE W. LIGHT DISPLAYED ON.  
01FEZ0024 C C/S CHECK ENGINE W. 600.00  
LIGHT DISPLAYED ON.

Tech(s): 9021

154490

12 S/PLUG CH A59GC

360.00

155788U

1 HARNESS/1-6

780.00

Pts: 1,140.00 Lbr: 600.00 Other: 0.00 Total Line A: 1,740.00

Story: SPARK PLUGS --- INSTALLED THE SD1 AND CHECKED ERRORS FOUND  
MISSFIRE ERRORS ON THE LEFT BANK. CHECKED SPARK FOUND A BAD  
WIRE ON CYLINDER 6. CHECKED THE SPARK PLUGS AND THEY ARE NOT  
THE FACTORY SPARK PLUGS AND ARE FOULING OUT. CHECKED  
COMPRESSION ON THE BANK AND IT IS GOOD. THEN INSTALLED 12  
NEW FACTORY SPARK PLUGS. THEN TEST DROVE AND VEHICLE RUN AT  
FACTORY SPCE. THEN THE DRIVER DOOR HANDLE BROKE REMOVED THE  
DOOR PANEL AND FIXED. ALL IS OPERATING AT THIS TIME.

~~~~~  
B C/S ENGINE HAS NOISE HEARD AT IDLE.
01FEZ0001 C C/S ENGINE HAS NOISE 0.00
HEARD AT IDLE.

Tech(s): 9021

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

Story: THE VEHICLE IN MISSFIRE SEE LINE 1

~~~~~  
C C/S TRANSMISSION FLUIDS LEAKS AT REAR VEHICLE AREA.  
03FEZ0029 C C/S TRANSMISSION 0.00  
FLUIDS LEAKS AT REAR  
VEHICLE AREA.

Tech(s): 9021

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

Story: TRANS PAN NOT TORQUED --- CHECKED THE TORQUE OF THE  
TRANSMISSION PAN AND SOME WERE NOT TORQUED. TORQUED THEN  
CLEANED AND INSTALLED TRACING POWDER AND TEST DROVE AND THEN  
LET THE VEHICLE SET OVER NIGHT AND NO LEAK AT THIS TIME.

~~~~~  
RO
MISC C SS 50.00
Pts: 0.00 Lbr: 0.00 Other: 50.00 Total Line 50.00
RO:

~~~~~  
Customer Pay

Labor

600.00

Parts

1,140.00

Lube

0.00

# Repair Order Detail - Customer Copy

|                           |          |
|---------------------------|----------|
| Sublet                    | 0.00     |
| Miscellaneous/Shop Charge | 50.00    |
| Deductible                | 0.00     |
| Total Charges             | 1,790.00 |
| Less Insurance/Adjustment | 0.00     |
| Sales Tax                 | 116.35   |
| Total                     | 1,906.35 |

# Repair Order Detail - Customer Copy

RO Number: 18275

RO Status: CLOSED

Customer:

Phone(s): Contact:

Vehicle: ZFFWL50A320126820

Main:

2002 456MGA

BLUE/

NATURAL

Mileage: 48,179

Service advisor: 8000

Tag number: T820

Payment type: CASH

Promised time: 06:00 PM

Promised date: 11/25/2014

Waiter: No

Estimate: 0.00

~~~~~

A	C/S OIL LEAK FROM FRONT ENGINE AREA.		
01FEZ0001	C	C/S OIL LEAK FROM FRONT ENGINE AREA.	3,465.00
Tech(s): 9021			
134714	1	SEALING RING	55.85
140753	2	GASKET	165.60
117275	7	O RING	111.44
163987	4	SEALING RING	161.00
140787	1	GASKET	23.41
187744	2	TIMING BELT	354.24
171057	2	BEARING/BALL **	294.68
114808	4	O RING	58.80
186922	2	FUEL FILTER **	176.40
10280060	4	WASHER/COPPER D. 14	13.20
113910	4	WASHER/COPPER	40.28
225462	2	GASKET	48.66
151562	2	FILTER/AIR	113.86
206166	2	OIL FILTER	74.40
199836	1	BELT POLY-V K5	42.79
201447	1	BELT DAYCO PV-K A	36.77
50044-1	10	OIL/5W40 QHP	149.90
4900-1	1	FLUID/BRAKE UB	39.80
4901-1	1	FLUID/PS S2	39.00
4903-1	1	COOLANT/ANTIFRZ	51.30
R134A	2	FREON/R134A	30.00
177298	1	GASKET	218.61
178159A	1	FILTER/TRANSMSN	118.41
178162A	1	FILTER/TRANSMSN	118.41
178100A	2	BUSHING/FILTER	99.68
14201980	5	RETAINING CLIP	1.70
140787	1	GASKET	23.41
Pts:	2,661.60	Lbr:	3,465.00
		Other:	0.00
		Total Line A:	6,126.60

Story: TIME AND LEAKS --- INSPECTED THE VEHICLE AND FOUND OIL LEAKING FROM THE CAM SEALS AND COVER, THE FRONT MAIN SEAL. PERFORMED A MAJOR SERVICE ON THE VEHICLE REMOVED ALL THE ENGINE COVER AND REMOVED THE INTAKE. THEN REMOVED THE VALVE COVERS AND CAMS. THEM RESEALED THE CAM SEALS AND CAM COVER. INSTALLED THE INTAKE A REPLACED THE TIMING BELTS AND BEARING. INSTALLED A NEW FRONT MAIN SEAL. THEN REPLACED THE AIR FILTER AND FUEL FILTER, INSTALL NEW COOLENT , AND POWER STEERING FLUID, AND OIL AND OIL FILTER. TEST DROVE THE VEHICLE AND TOPED OFF ALL FLUIDS ALL IS OPERATING AT FACTORY SPCE AT THIS TIME.

Repair Order Detail - Customer Copy

RO Number: 18275

RO Status: CLOSED

Customer:

Phone(s): Contact:

Vehicle: ZFFWL50A320126820

Main:

2002 456MGA

Cell:

BLUE/
NATURAL

Mileage: 48,179

Service advisor: 8000

Tag number: T820

Payment type: CASH

Promised time: 06:00 PM

Promised date: 11/25/2014

Waiter: No

Estimate: 0.00

~~~~~  
B C/S OIL LEAK FROM REAR TRANSMISSION AREA.  
05FEZ C C/S OIL LEAK FROM 534.60  
REAR TRANSMISSION  
AREA.

Tech(s): 9021

80790

177783

8 FLUID/ATF

1 RADIO/BECKER

79.92

1,000.00

Pts: 1,079.92 Lbr: 534.60 Other: 0.00 Total Line B: 1,614.52

Story: PAN GASKIT LEAKING --- OIL IS COMING FROM THE FROM  
TRANSMISSION WEEP HOLE, AND THE PAN GASKET. REMOVED THE  
TRANS OIL PAN AND REPLACED THE TWO TRANS FLITERS. THEN  
RESEALED THE PAN AND FILLED WITH FLUID. TEST DROVE AND ALL  
IS OPERATING AT FACTORE SPCE AT THIS TIME.

~~~~~  
C TRANSPORT VEHICLE FROM CLIENT HOME TO DEALER.
11FEZ002 C TRANSPORT VEHICLE 0.00
FROM CLIENT HOME TO
DEALER.

Tech(s): 8000

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

Story: TOWING FROM CLIENT HOME TO FCF AND RETURN TO CLIENT AT NO
CHARGE.

~~~~~  
RO  
MISC C SS 50.00  
Pts: 0.00 Lbr: 0.00 Other: 50.00 Total Line  
RO: 50.00  
~~~~~

Customer Pay

Labor 3,999.60

Parts 3,741.52

Lube 0.00

Sublet 0.00

Miscellaneous/Shop Charge 50.00

Deductible 0.00

Total Charges 7,791.12

Less Insurance/Adjustment 0.00

Sales Tax 492.47

Total 8,283.59